

Department of Energy

Idaho Operations Office 850 Energy Drive Idaho Falls, Idaho 83401-1563

October 29, 2002

Mr. Wayne Pierre, Team Leader Environmental Cleanup Office U.S. Environmental Protection Agency Region X 1200 Sixth Avenue Seattle, Washington 98101

Mr. Dean Nygard, Site Remediation Manager Idaho Department of Environmental Quality 1410 N. Hilton
Boise, Idaho 83706

SUBJECT:

Transmittal of the Technical Support Facility-06 and Technical Support Facility-

26 Calendar Year 2000 Sampling and Remediation Summary Report for Waste

Area Group 1, Operable Unit 1-10 (EM-ER-02-185)

Dear Mr. Pierre and Mr. Nygard:

The subject report is enclosed. The report summarizes the sampling activities, the analytical results from the sampling, and the remediation that was performed for these sites. Please contact me at (208) 526-4392 or Mark Shaw at (208) 526-6442 with any questions.

Sincerely,

Kathleen E. Hain, Manager

Environmental Restoration Program

Enclosure

cc: C. Cody, DEQ, 1410 N. Hilton, Boise, ID 83706

M. Wilkening, EPA Region X, Idaho Ops Office, 1435 N. Orchard St., Boise, ID 83706